U.S. _fficials Only CONFIDENTIAL

SECURIT: INFORMATION

CENTRAL INTELLIGENCE AGENCY

INFORMATION REPORT

COUNTRY Brazil

SUBJECT Salvador (Bahia) Harbor/Landing Facilities/Storage Facilities/Operations and Capacity/Supplies and Utilities/Repair Facilities

PLACE ACQUIRED

DATE ACQUIRED (BY SOURCE)

DATE (OF INFO.

PHIS DOCUMENT CONTAINS IMPORMATION APPECTING THE NATIONAL DEFENSE OF THE UNITED STATES, SITHIN THE MEASURE OF TITLE 18. SECTIONS 783 AND 784, OF THE U.S. COSE, AS AMENDED. ITS TRANSMISSION OF REVEL LATION OF ITS CONTENTS TO ON ACCEPT BY AN UNAUTHORIZED PERSON IS PROMISETED BY LAK. THE SEPRODUCTION OF THIS REPORT IS RESPONSELYED.

THIS IS UNEVALUATED INFORMATION

DATE DISTR. /5 May 53

25X²

NO. OF PAGES 2

NO. OF ENCLS.

SUPP. TO REPORT NO.

The Office of Naval Intelligence furnished the following information to CIA for IAC dispersionation in accordance with paragraph 3c c "SCID #7. This report was obtained by DIO-3ND and rorwarded as ONI report 61-C-53/

- 1. Harbor: The least depth of water over the bar at low water is 60 feet. The least depth at safe anchorage at low water is 30 feet. Water at dockside is salt; the bottom is sand and affords good holding ground. Currents are negligible. The port can be entered safely at night, pilots are considered to be skillful.
- 2. Landing Facilities: The largest tug available is of 750 HP and is diesel-powered. Its services are not considered necessary in docking and undocking. The nearest salvage boat is at Rio de Janeiro. There are about 30 wooden shows used as lighters, total capacity 800 tons. There are twelve electric craces on the docks, six having a capacity of 1½ tons each, four having a capacity of 3 tons each and two having a capacity of 5 tons each. There is one steam-powered floating crane, capacity 85 tons. It has a maximum cutreach of 32 feet, and can plumb the held of a C+2 type ship with maximum freeboard of 24 feet. large fonders are needed when the ship's draft is over 24 feet.
- 3. Storage Facilities: There are three covered warehouses with a total of 69,600 eq ft of floor space adjacent to Pertho No 7 and No 8. There are 68,000 to ft of refrigorated storage space available in the port where temperatures of 32°F-10°F can be maintained. There are two grain elevators.
- Operations and Capacity: An adequate labor supply is available. The sustomary number of men per gang is 13, ylus a foreman and 8 men on the dock. The average tens per gang hour loading are as follows: 15 tens of scoon takes 12 tens of scoon saster seed; 10 tens of scoon butter, 1; tens of tens of scoon takes 12 tens of scoon saster seed; 10 tens of scoon butter, 1; tens of tens of scoon takes 12 tens of scoon saster seed; 10 tens of scoon butter, 1; tens of tens of scoon takes 12 tens of scoon saster seed; 10 t
- 5. Supplies and Utilities: Fresh water can be obtained from the dock at the rate of 15-20 tons per bour; the vater is poor for drinking bur good for boilers. Fuel, oil is obtainable at an initialization and can be delivered at the rate of 100 bblr per hour. Presh vegetables, fruits, meats, and dry stire. On be purthased in small quantities at high prices. Ballast cannot be obtained. There are adequate hospital

U.S. Officials Only CONFIDENTIAL ONI review(s) completed.

This report is for the use within the USA of the Intelligence components of the Departments or

This report is for the use within the CSA of the Intelligence components of the Department of Agencies indicated above. It is not to be transmitted overseas without the concurrence of the originating office through the Assistant Director of the Office of Collection and Dissemination, CIA

25X1

. 25X1

Approved For Release 2008/03/03 : CIA-RDP85T00875R002000110030-0

Approved For Release 2008/03/03: CIA-RDP85T00875R002000110030-0

CONFIDENTIAL/US OFFICIALS ONLY Security Information

-2-

25X1

i'acilities and there are doctors and dentists available.

6. Repair Facilities: There are no divers or drydocks at the port; the nearest drydock is at Rio de Janeiro. Minor hull, engine and electrical repairs can be made. Repairs cannot be made to gyro compass, radio direction finder, radio equipment, fathometer and similar equipment.

-end-

CONFIDENTIAL/UD OFFICIALS ONLY Security Information

1